



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Report Date: October 26, 2006

Supervisor 1002

Mine Name: Anval 1 & 2

Operator Name:

Steven Gale

PO Box 855

Beaver, UT 84713

Inspector(s): Daron Haddock and Dan Smith

Other Participants: none

Mine Status: Active

Permit number: S010038

Inspection Date: October 16,
2006

Time: 5:15 PM to 5:30 PM

Weather: a few clouds, cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: routine inspection completed while in the area.

Directions to Site: Go north of Minersville on dirt/gravel road approximately 3 miles. Turn to the right and follow road to mine.

Inspection Summary:

1. The permit fee was paid on August 24, 2006.
6. A portion of this site has been reclaimed and the vegetation is coming in. Dan's GPS data show that .53 acres has been released.
7. There is a track hoe on site and some evidence of recent excavation although no activity was occurring at the time of the inspection. Dan Smith GPS'd the area of disturbance and identified .37 acres being utilized. Pictures were taken of the disturbed area and they show the extent of the disturbance. The pit is fairly shallow and I saw no concern with deleterious materials or safety hazards.

Conclusions and Recommendations:

Should continue to monitor the site when in the area. The reclamation bond needs to have the Division named as a beneficiary.

Inspection Date: October 16, 2006; Report Date: October 26, 2006
Page 2 of 2
S/001/038

Inspector's Signature Caron R Haddock Date: 10/26/06

DRH:pb
cc: Operator
(BLM)
Attachment: Map & Photos

P:\GROUPS\MINERALS\WP\M001-Beaver\S0010038-Anval\inspections\insp-10162006.doc

Anval 1&2 mine, S/001/038, October 16, 2006



